

8/23/2016, Rachel Savich Oser, Fbk. 48, pg. 4


7/25/2018, Cassidy Raley, Fbk. 52, pg. 22

Monument recovered in good condition, 0.2' below grade

Corner I.D. # 107T

MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 33, Township 8N, Range 1E,**Monument Description & Remarks:** 2-1/2" Aluminum Monument, 30" long, set 0.1' below grade.(This monument is not a PLSS corner. It was set as part of a Geodetic Control Survey.)

I, Matthew L. Cooper, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 9th day of June, 2004 A.D.

Matthew L. Cooper
 Indiana Registered Land Surveyor No. LS20200079

COMPLETED By *Steve Tanks*





0 50 100 200 Feet



Office of the Monroe County Surveyor
2004 Geodetic Control Project

119 West 7th Street
Bloomington, Indiana 47404
(812) 349-2570

ImageSource: 2014 Monroe County Pictometry

Document Path: N:\Surveyor_Office\MCS_SurveyProjectFiles\MonroeCounty_GeodeticControlNetwork\2016 Control Check\draw\MCSO_GeodeticControlNetwork_Aerials.mxd Date Saved: 5/30/2017



